

TRACK INSPECTION REPORTING FORM

Name Michael Ballard

Date 7-15-2013

Page 1 of 1

(Please Print)
Watchman Greenwood

Inspected From Hunt Valley

To Luthersville

W.O Number 1150903

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.						698-1A	S306	320	Y	N
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

Loose jam nut throw rod.

Track inspection complete

Were Switch in the area of Inspected

Yes ☒

NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☐

SPECIAL INSPECTION

Yes ☐

NO ☐

Reason for special Inspection ? _____

Track Inspector Signature

Michael Ballard

Supervisory Certification

[Signature]

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1150903 TEAM ONE - SECT 1: HV/LU - CM 902N TO Site: LTRAIL
Classification: MTA \ LTRAIL MTA - LTRAIL Status: CLOSE
Asset: Priority: 1
Alias: Work Type: PM
Location: CHAIN_MARK LT Rail Chain Markers Crew: DAY-A
Work Location: Warranty Situation Present?: N
Work Group: MTA527 Maintenance Alert? ☐

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	420.64
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	07/15/13 12:31:19 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-####-052			

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	CLOSE

ibor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/15/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WGREENWOOD	<input checked="" type="checkbox"/>	07/15/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name N. I. Skovgaard

Date 07-16-13

Page 1 of 1

Watchman T. Schuster

Inspected From Cynthia U. Irie

To

Cold Spring

W.O Number 1150049

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

Track Inspection Completed - No defects noted.

Were Switch in the area of Inspected all single operating ☒ Yes ☐ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO ☒

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification _____

Walter W. Bryant

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: TEAM TWO - SECT 2: LU/CS - CM 586N TO
 Classification: MTA - LTRAIL
 Asset:
 Alias:
 Location: LT Rail Chain Markers
 Work Location:
 Work Group*:

Site:
 Status:
 Priority:
 Work Type*:
 Crew:
 Warranty Situation Present?:
 Maintenance Alert?: ☐

Work Details

Component:
 Position:
 Reason for Repair:
 Work Accomplished:
 Part Failure:
 Parent WO:
 Telematics Code:
 Telematics Transaction:
 GL Account:

Total Planned Cost:
 Total Actual Cost:
 Repair Limit Amount:
 Reported By:
 Reported Date:

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD	<input type="text"/>	<input type="text"/>	N			NONE	COMP

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	<input checked="" type="checkbox"/>	07/16/13	06:00:00	02:00:00	8:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	07/16/13	06:00:00	02:00:00	8:00	26.29	N	N/A

TRACK INSPECTION REPORTING FORM

Name Michael L Ballard

Date 7-16-2013

Page / of

Watchman Greenwood

Inspected From Cold spring

To Camden yard Penn Ln

W.O Number 1150122

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.				1	(W)	88-3A	R-302	301	Y	N
2.	92+00	99+80		1	(W)		R-301	307	Y	N
3.	78+80			1+2			R-301	327	Y	N
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

[illegible]

Were Switch in the area of Inspected ☒ Yes ☐ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO _____

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification _____

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action [Icons]

Quick Reporting Specifications

Work Order	1150122	TEAM ONE - SECT 3: CS/CY/PENN - CM 23	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type*	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	DAY-A
Work Location			Warranty Situation Present?	N
Work Group*	MTA527		Maintenance Alert?	<input type="checkbox"/>

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	630.96
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	07/14/13 12:52:07 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-####-052			

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Download

Tasks Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDART			N			NONE	COMP

Labor Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	07/16/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WGREENWOOD	<input checked="" type="checkbox"/>	07/16/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	RNELSON1	<input checked="" type="checkbox"/>	07/16/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Labor Materials Tools Failure Reporting

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name Richard Nelson
(Please Print)

Date 7-17-13

Page 1 of 1

Vatchman

Inspected From

Linthicum

To

Cornwell + BWT

W.O Number

1149314

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail EW	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

No New Defects Noted

Riding Inspection due
To extreme heat

Were Switch in the area of Inspected

Yes

NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☒

SPECIAL INSPECTION

Yes

NO ☒

Reason for special Inspection ?

Track Inspector Signature

Richard Nelson

Supervisory Certification

M. Bayle

Quick Reporting (Tr)

Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find:

Select Action

Quick Reporting

Specifications

Work Order 1149314 TEAM ONE - SECT 5 - CM 355S/488S AND
Classification MTA \LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARK LT Rail Chain Markers
Work Location
Work Group MTA527

Site LTRAIL
Status COMP
Priority 1
Work Type PM
Crew
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-####-052

Total Planned Cost 0.00
Total Actual Cost 210.32
Repair Limit Amount
Reported By MTACRON
Reported Date 07/13/13 12:30:16 AM

Asset Details

Primary Meter

Multiple Assets, Locations and Cls Filter

Tasks Filter 1 - 2 of 2

Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

Task Information

Task 10 ESTABLISH ON TRACK SAFETY PER RPW
Component
Position
Reason for Repair
Work Accomplished
Part Failure

Warranty? N
Estimated Duration 0:00
Sequence 10
Inherit Status Changes?
Accepts Charges?

Work Reference Information

Reference WO 1149315
Status COMP
Asset
Alias
Location CHAIN_MARK LT Rail Chain Markers
Service Group
Service

Qualifications

Qualifications NONE
Met on Actual Labor? N/A
Met on Assignments? N/A
Met on Planned Labor? N/A

Attachment Information

Attachments

Scheduling Information

Target Start 07/18/13 12:00:00 AM
Target Finish 07/18/13 12:00:00 AM
Scheduled Start
Scheduled Finish

Actual Start 07/19/13 01:40:15 PM
Actual Finish 07/19/13 01:40:15 PM
Time Remaining

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1

Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	RNELSON1		07/17/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Labor

Task
Labor RNELSON1 Richard Nelson
Regular Hours 8:00
Component

Start Date 07/17/13
Start Time 07:00:00
End Date 07/17/13
End Time 03:00:00

Warranty? N
Qualification Met? N/A
Approved?
Timer Status

TRACK INSPECTION REPORTING FORM

Name W. Bryant

Date 07-18-13

Page 1 of 1

(Please Print)

Watchman D. Boyd

W.O Number 1148129

Inspected From Hunt Valley

To Lutheville

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	EW	No.	Comp.	Defect	S/Y/R	Y/N
1.	<u>718+25</u>	<u>—</u>	<u>—</u>	<u>2</u>	<u>4w</u>	<u>—</u>	<u>W-301</u>	<u>329</u>	<u>Y</u>	<u>Y</u>
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	<u>At cm 718+25 North of Texas Rd xing 8 ties in a row are pumping 1" under load. Need 1 bucket of ballast ("0681) Area is mark on East retaining wall & ties with yellow chalks</u>

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☒ NO ☐

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

Walter W. Bryant

Supervisory Certification

[Signature]

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: [] Select Action []

st Quick Reporting Specifications

Work Order	1148129	TEAM TWO - SECT 1: HV/LU - CM 902N TO	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	APPR
Asset			Priority	1
Alias			Work Type *	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group *	MTA527		Maintenance Alert?	

Work Details

Component	
Position	
Reason for Repair	
Work Accomplished	
Part Failure	
Parent WO	
Telematics Code	
Telematics Transaction	
GL Account	J05-####-052

Total Planned Cost	0.00
Total Actual Cost	210.32
Repair Limit Amount	
Reported By	MTACRON
Reported Date	07/12/13 12:45:13 AM

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	APPR

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	✓	07/18/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

lame

Rolland Greenwood

Date _____

7-18-2013

Page 1 of 1

(of)

Watchman

(Please Print)

Nelson

Inspected From

Lathesville

To

Cold spring

W.O Number

1148136

[illegible]

Item	COMMENTS
------	----------

No New defects Found

Track inspection is complete

Were Switch in the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

Quick Reporting (Tr)

 Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Work Details		Financials	
Component	<input type="text"/>	Total Planned Cost	<input type="text" value="0.00"/>
Position	<input type="text"/>	Total Actual Cost	<input type="text" value="630.96"/>
Reason for Repair	<input type="text"/>	Repair Limit Amount	<input type="text"/>
Work Accomplished	<input type="text"/>	Reported By	<input type="text" value="MTACRON"/>
Part Failure	<input type="text"/>	Reported Date	<input type="text" value="07/12/13 12:45:36 AM"/>
Parent WO	<input type="text"/>		
Telematics Code	<input type="text"/>		
Telematics Transaction	<input type="text"/>		
GL Account	<input type="text" value="J05-####-052"/>		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Labor Materials Tools Failure Reporting

Labor										Filter		1 - 3 of 3		Download	
Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?						
	MPOLLARD	✓	07/18/13	07:00:00 F	03:00:00 F	8:00	26.29	N	N/A						
	WGREENWOOD	✓	07/18/13	07:00:00 F	03:00:00 F	8:00	26.29	N	N/A						
	RNELSON1	✓	07/18/13	07:00:00 F	03:00:00 F	8:00	26.29	N	N/A						

Task			Start Date	07/18/13	Warranty?	N
Labor	MPOLLARD	Michael Pollard	Start Time	07:00:00	Qualification Met?	N/A
Regular Hours	8:00		End Date	07/18/13	Approved?	<input checked="" type="checkbox"/>
Component			End Time	03:00:00	Timer Status	
Position			Rate	26.29	Craft	AREPAIR
Reason for Repair			Line Cost	210.32	Skill Level	
Work Accomplished			Type	WORK		
Part Failure						
Memo						

Outside Labor		Premium Pay		Charge Information	
Outside?	<input type="checkbox"/>	Premium Pay Code	<input type="text"/>	GL Debit Account	J05-#### 052
Vendor	<input type="text"/>	Premium Pay Hours	<input type="text"/>	GL Credit Account	<input type="text"/>
Contract	<input type="text"/>	Premium Pay Rate	<input type="text"/>	Location	CHAIN MARKI
Revision	<input type="text"/>	Premium Rate Type	<input type="text"/>	Asset	<input type="text"/>
				Alias	<input type="text"/>
				Recorded as Received	<input type="text"/>
				<input type="button" value="Select Labor"/> <input type="button" value="Select Planned Labor"/> <input type="button" value="New Row"/>	

TRACK INSPECTION REPORTING FORM

Name Richard Nelson

Date 7-19-13

Page 1 of 1

(Please Print)

Watchman W. Greenwood

W.O Number 1148062

Inspected From Condon

To Linthicum

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.	83+80s	84+00		2	E/W		W301	329	Y	
2.	150+50s			2	E		M307	316	Y	
3.	186+70s			2	E		M312	316	Y	
4.	83+80s	84+00		2	E/W		W301	327	Y	
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

144	South end of Middle branch, (speed restriction in place)
2	CSX bridge 9 cribs in-a-row on east rail side.
3	Berm on east shoulder no ballast 6 ties in-a-row, bottom of concrete ties is showing, needs ballast ASAP, on a curve.

Were Switch In the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☐ NO ☒

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature Richard Nelson

Supervisory Certification [Signature]

Quick Reporting (Tr)

Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting

Specifications

Work Order	1148062	TEAM ONE - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL
Classification	MTA LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/12/13 12:41:45 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and Cls Filter

Tasks Filter

1 - 2 of 2

Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Task Information

Task	10	ESTABLISH ON TRACK SAFETY PER RPW	Warranty?	N
Component			Estimated Duration	0:00
Position			Sequence	10
Reason for Repair			Inherit Status Changes?	✓
Work Accomplished			Accepts Charges?	✓
Part Failure				

Work Reference Information

Reference WO	1148063	
Status	COMP	
Asset		
Alias		
Location	CHAIN_MARK	LT Rail Chain Markers
Service Group		
Service		

Qualifications

Qualifications	NONE
Met on Actual Labor?	N/A
Met on Assignments?	N/A
Met on Planned Labor?	N/A

Attachment Information

Attachments

Scheduling Information

Target Start	07/19/13 12:00:00 AM	Actual Start	07/20/13 08:59:17 AM
Target Finish	07/19/13 12:00:00 AM	Actual Finish	07/20/13 08:59:17 AM
Scheduled Start		Time Remaining	
Scheduled Finish			

New Row

Labor Materials Tools Failure Reporting

Labor Filter

1 - 2 of 2

Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	RNELSON1	✓	07/19/13	07:00:00 A	03:00:00 F	8:00	26.29	N	N/A
	WGREENWOOD	✓	07/19/13	07:00:00 A	03:00:00 F	8:00	26.29	N	N/A

Labor

Task		Start Date	07/19/13	Warranty?	N	
Labor	RNELSON1	Richard Nelson	Start Time	07:00:00 A	Qualification Met?	N/A
Regular Hours	8:00	End Date	07/19/13	Approved?	✓	

TRACK INSPECTION REPORTING FORM

Name Walter W. Bryant

Date 67-19-13

Page 1 of 1

(Please Print)

Watchman M. Pollard

W.O Number 114 79 87

Inspected From

To

To Cold Spring
Perpetua

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch In the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO

SPECIAL INSPECTION Yes NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification

Value 4.13 g

Quick Reporting (Tr)

Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1147987 TEAM TWO - SECT 3 - CM 235N/16S AND
Classification: MTA \ LTRAIL MTA - LTRAIL
Asset:
Alias:
Location: CHAIN_MARK LT Rail Chain Markers
Work Location:
Work Group: MTA527
Site: LTRAIL
Status: COMP
Priority: 1
Work Type: PM
Crew:
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component	<input type="text"/>	Total Planned Cost	0.00
Position	<input type="text"/>	Total Actual Cost	420.64
Reason for Repair	<input type="text"/>	Repair Limit Amount	<input type="text"/>
Work Accomplished	<input type="text"/>	Reported By	MTACRON
Part Failure	<input type="text"/>	Reported Date	07/12/13 12:37:42 AM
Parent WO	<input type="text"/>		
Telematics Code	<input type="text"/>		
Telematics Transaction	<input type="text"/>		
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and Cls Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Task Information

Task: 10 ESTABLISH ON TRACK SAFETY PER RPW
Component:
Position:
Reason for Repair:
Work Accomplished:
Part Failure:
Warranty: N
Estimated Duration: 0:00
Sequence: 10
Inherit Status Changes? ☒
Accepts Charges? ☒

Work Reference Information

Reference WO: 1147988
Status: COMP
Asset:
Alias:
Location: CHAIN_MARK LT Rail Chain Markers
Service Group:
Service:

Qualifications

Qualifications: NONE
Met on Actual Labor? N/A
Met on Assignments? N/A
Met on Planned Labor? N/A

Attachment Information

Attachments

Scheduling Information

Target Start: 07/19/13 12:00:00 AM
Target Finish: 07/19/13 12:00:00 AM
Scheduled Start:
Scheduled Finish:
Actual Start: 07/19/13 02:50:23 PM
Actual Finish: 07/19/13 02:50:23 PM
Time Remaining:

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	✓	07/19/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WBRYANT	✓	07/19/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Labor

Task:
Labor: MPOLLARD Michael Pollard
Regular Hours: 8:00
Start Date: 07/19/13
Start Time: 07:00:00
End Date: 07/19/13
Warranty: N
Qualification Met: N/A
Approved: ☒

TRACK INSPECTION REPORTING FORM

• Walter W. Bryant

Date 07-20-2013

Page 1 of 1

(Please Print)

Watchman

HA

Inspected From

Linthicum

To

Cremwell

W.O Number

1148073

[illegible]

Item	COMMENTS
------	----------

Riding inspection -

Were Switch In the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

North W. B. Grant

ing (Tr)

Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find:

Select Action

Quick Reporting

Specifications

Work Order 1148073 TEAM TWO - SECT 5: LINT/CROM - CM 355
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARK LT Rail Chain Markers
Work Location
Work Group MTA527

Site LTRAIL
Status COMP
Priority 1
Work Type* PM
Crew
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-####-052

Total Planned Cost 0.00
Total Actual Cost 210.32
Repair Limit Amount
Reported By MTACRON
Reported Date 07/12/13 12:42:20 AM

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	✓	07/20/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Labor

Task
Labor WBRYANT Walter Bryant
Regular Hours 8:00
Component
Position
Reason for Repair
Work Accomplished
Part Failure
Memo

Start Date 07/20/13
Start Time 06:00:00
End Date 07/20/13
End Time 02:00:00
Rate 26.29
Line Cost 210.32
Type WORK

Warranty? N
Qualification Met? N/A
Approved? ✓
Timer Status
Craft AREPAIR
Skill Level

Outside Labor

Outside?
Vendor
Contract
Revision

Premium Pay

Premium Pay Code
Premium Pay Hours
Premium Pay Rate
Premium Rate Type

Charge Information

GL Debit Account J05-####-052
GL Credit Account
Location CHAIN_MARK
Asset
Alias
Recorded as Received

Select Labor

Select Planned Labor

New Row